

ACCESSORY

Computer-USB-connection set PC-BOX

for MAURER pyrometers series 1000 / 2000

- With integrated power supply for pyrometer supply: 100 – 270 VAC / 24 VDC
- Pyrometer connection via 12-pol. SUB-D or 10-pol. terminal
- Output of pyrometer interface via 3-pol. jack socket
- Choose between two connection cables:
 - 2 m connection cable 12-pole to 15-pole SUB-D
 - Interface converter RS232 or RS485 to USB



Type with USB (interface converter)

Terminal assignment

1	+ 24 VDC
2	Limit value(open collector)
3	RS232 TXD (RS485 - B)
4	RS232 RXD (RS485 - A)
5	RS232 GND
6	GND (24 VDC)
7	GND
8	Control input. Choose between storage reset, external light beam, software IR-LOG start-stop
9	Output 0 – 20 mA
10	PE (ground)